

FIG. 1

FleetCross SEARCH METHODS FILE EDIT TOOLS HELP		
PARTS & LABOR GENERATOR		
VIN: (ENTER LAST SIX DIGITS):		UNIT NUMBER:
1FVYSBZYL648309		022352
MANUFACTURER:		
FREIGHTLINER CORPORATION—FRGT		
MODEL OR COMPONENT:		
CENTURY CLASS-CONV CEN DDE		
VEHICLE SYSTEM:		
011001—AXLE - FRONT-NON-DRIVEN 013001—BRAKES AND DRUMS - FRONT 013002—BRAKES AND DRUMS - REAR 013005—BRAKE PEDAL ASSEMBLY 013007—BRAKE LINES AND FITTINGS-HYDRAULIC AND AIR 013009—COMPRESSOR-AIR 013010—BRAKES - AIR 013011—BRAKES - ANTI-LOCK		
PART NUMBER	PART DESCRIPTION	PART MFR.
LATIN OPERATIONS PER APPLICATION DESCRIPTION		
SRT CODE		SRT DESCRIPTION

FIG. 2

FleetCross		SEARCH METHODS FILE EDIT TOOLS HELP	
PARTS & LABOR GENERATOR			
VIN: ENTER LAST SIX DIGITS:		UNIT NUMBER:	
1FV5SEB2YL648309		022352	
MANUFACTURER:			
FREIGHTLINER CORPORATION—FRGHT			
MODEL OR COMPONENT:			
CENTURY CLASS-LOON/GEN DDE			
VEHICLE SYSTEM:			
011001—AXEL-FRONT, NON-DRIVEN			
PARTS APPLICATION DESCRIPTION		REPAIR TIME APPLICATION	
FF-981, S. C1, S31L1447H46IS		FRONT AXLE KNUCKLE SPIN	
SPNDL NUT/TRB RS S 4 PC		FRONT AXLE KNUCKLE STC	
		FRONT AXLE SCREW	
		DAMAGE GROUP	
		400-002541	
		400-002560	
		400-000578	
PARTS PER APPLICATION DESCRIPTION:			
PART NUMBER	PART DESCRIPTION	PART MFR	
MOTOR OPERATIONS PER APPLICATION DESCRIPTION:			
SRT CODE:	SRT DESCRIPTION		

FIG. 3

FleetCross		SEARCH METHODS FILE EDIT TOOLS HELP	
PARTS & LABOR GENERATOR			
VIN: (ENTER LAST SIX DIGITS):		UNIT NUMBER:	
1FYSSEBYLG48309		022352	
MANUFACTURER:			
FREIGHTLINER CORPORATION—FRGHT			
MODEL OR COMPONENT:			
CENTURY CLASS-LOONY GEN DDE			
VEHICLE SYSTEM:			
011001—AXEL-FRONT, NON-DRIVEN			
PARTS APPLICATION DESCRIPTION		REPAIR TIME APPLICATION	
FF-381, S, G1, S311, 1444746HS		FRONT AXLE KNUCKLE SPIN 400-002541	
SPINDL NUT/FRBS, S,4 PC		FRONT AXLE KNUCKLE STC 400-002560	
		FRONT AXLE SCREW 400-000378	
PARTS PER APPLICATION DESCRIPTION:			
PART NUMBER	PART DESCRIPTION	PART MFR	
TDA A3 3111W377	KNUCKLE ASSY LH	FRGHT	
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT	
TDA 3101Z1088	PIN-KNUCKLE	FRGHT	
LABOR OPERATIONS: PER APPLICATION DESCRIPTION:			
SRT CODE:		SRT DESCRIPTION	

FIG. 4

FleetCross		SEARCH METHODS FILE EDIT TOOLS HELP	
		PARTS & LABOR GENERATOR	
VIN: (ENTER LAST SIX DIGITS):		UNIT NUMBER:	
1FYSSEB2YL6H8309		022352	
MANUFACTURER:			
FREIGHTLINER CORPORATION—FRGHT			
MODEL OR COMPONENT:			
CENTURY CLASS-LOONV CEN DDE			
VEHICLE SYSTEM:			
011001—AXEL-FRONT, NON-DRIVEN			
PARTS APPLICATION DESCRIPTION		REPAIR TIME APPLICATION	
FF-981, S, GC1, 6311144746HS		FRONT AXLE KNUCKLE 9PIN 400-002541	
SPNDL NUT/FRB RS, S,4 PC		FRONT AXLE KNUCKLE, STC 400-002560	
		FRONT AXLE SCREW 400-000578	
PARTS PER APPLICATION DESCRIPTION:			
PART NUMBER	PART DESCRIPTION	PART MFR	
TDA A3 3111W3377	KNUCKLE ASSY LH	FRGHT	
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT	
TDA 3107Z1088	PIN-KNUCKLE	FRGHT	
LABOR OPERATIONS PER APPLICATION DESCRIPTION:			
SRT CODE	SPT DESCRIPTION		
400-0000	ACTUAL TIME		
400-0050A	STEERING KNUCKLE, R/R		
400-0050B	STEERING KNUCKLES, 2/R/R		

FIG. 5

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
<div> </div>							
1000							
WORK SUMMARY NUMBER:		DATE CREATED:		CUSTOMER NAME:			
1000		10032001					
VIN:				UNIT NUMBER:			
1FUYSEB2YL646308				022352			
MANUFACTURER:							
FREIGHTLINER CORPORATION-FRGHT							
MODEL OR COMPONENT:							
CENTURY GLASS-CONV. CEN DDE							
PARTS USED:							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001	1			
PF: (PRIMARY FAILED ITEM):							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
LABOR SUMMARY:							
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS			
PRIMARY DAMAGE CODE: <input type="text"/>							
CAMPAIGN NUMBER: <input type="text"/>							
TOTAL HOURS: 0.00							

FIG. 6

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
<div> </div>							
1000							
WORK SUMMARY NUMBER:		DATE CREATED:		CUSTOMER NAME:			
1000		10/03/2001					
VIN:		UNIT NUMBER:					
1FUYSEB27L646309		022352					
MANUFACTURER:							
FREIGHTLINER CORPORATION-FRHT							
MODEL OR COMPONENT:							
CENTURY GLASS-CONV. CEN TIDE							
PARTS USED:							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001	1			
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1			
PFI: PRIMARY FAILED ITEM:							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1			
LABOR SUMMARY:							
DAMAGE CODE	ISRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS			
PRIMARY DAMAGE CODE:		COMPONENT NUMBER:		TOTAL HOURS:		0.00	

FIG. 7

REPAIR DATE
PLEASE ENTER THE REPAIR DATE AS MMDDYYYY; THEN PRESS ENTER TO CONTINUE:
09/24/2001
<input type="button" value="CANCEL"/>

FIG. 8

DAMAGE REASON SELECTION	
*SINGLE CLICK THE DAMAGE REASON CODE TO CONTINUE:	
DAMAGE CODE	DESCRIPTION
130	BROKEN
740	WORN
850	LOOSE
<input type="button" value="CANCEL"/>	

FIG. 9

FleetCross		SEARCH METHODS FILE EDIT TOOLS HELP	
1000		x	
WORK SUMMARY NUMBER: 1000		DATE CREATED: 10/03/2001	
VIN: 1FUYSEB21G46309		CUSTOMER NAME:	
MANUFACTURER: FREIGHTLINER CORPORATION-FRHT		UNIT NUMBER: 022352	
MODEL OR COMPONENT: CENTURY GLASS-GONV. CEN TDE			
PARTS USED:			
PART MFR	PART NUMBER	PART DESCRIPTION	VARS CODE QTY.
FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001 1
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001 1
PF: (PRIMARY FAILED ITEM):			
PART MFR	PART NUMBER	PART DESCRIPTION	VARS CODE QTY.
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001 1
LABOR SUMMARY:			
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VARS CODE HOURS
400-002541740	1400-0050B	STEERING KNUCKLES 2 R/R	011001 5.20
PRIMARY DAMAGE CODE: 400-002541740		CAMPAIGN NUMBER:	
		TOTAL HOURS: 5.20	

FIG. 10

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
<div> </div>							
1000							
WORK SUMMARY NUMBER:		DATE CREATED:		CUSTOMER NAME:			
1000		10/03/2001					
VIN:		UNIT NUMBER:					
1FUYSEB2YL646309		022352					
MANUFACTURER:							
FREIGHTLINER CORPORATION—FRGHT							
MODEL OR COMPONENT:							
CENTURY GLASS-CONV. CEN DDE							
PARTS USED:							
PART MFR	PART NUMBER	PART DESCRIPTION	WMRS CODE	QTY.			
FRGHT	TDA A3 311W3377	KNUCKLE ASSY LH	011001	1			
FRGHT	TDA A3 311T3400	KNUCKLE ASSY RH	011001	1			
PF: PRIMARY FAILED ITEM:							
PART MFR	PART NUMBER	PART DESCRIPTION	WMRS CODE	QTY.			
FRGHT	TDA A3 311T3400	KNUCKLE ASSY RH	011001	1			
LABOR SUMMARY:							
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	WMRS CODE	HOURS			
400-002547740	400-00500B	STEERING KNUCKLES 2/R/R	011001	5.20			
PRIMARY DAMAGE CODE:		CAMPAIGN NUMBER:		TOTAL HOURS:			
400-002547740				5.20			

FIG. 11

FreeCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
<div> </div>							
1000		WORK SUMMARY NUMBER:		DATE CREATED:		CUSTOMER NAME:	
		1000		10/3/2001			
VIN:		UNIT NUMBER:					
1FYSSEB2YL646309		022352					
MANUFACTURER:							
FREIGHTLINER CORPORATION-FRGHT							
MODEL OR COMPONENT:							
CENTURY GLASS-CONV. CEN DDE							
PARTS USED:							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 311TW3377	KNUCKLE ASSY LH	011001	1			
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1			
PF1: PRIMARY FAILED ITEM:							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1			
LABOR SUMMARY:							
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS			
400-002541740	400-0050B	STEERING KNUCKLES 2 R/R	011001	5.20			
PRIMARY DAMAGE CODE:		CAMPAIGN NUMBER:	TOTAL HOURS:				
400-002541740			5.20				

FIG. 12




FIG. 13




FIG. 20

FREIGHTLINER QUICKCLAIM									
DEALER CODE	XXXX	CLAIM TYPE	WAR	LOCATION	XXXXXXXXXX	CUSTOMER NAME	XXXXXXXXXXXX	EXCP	
022352	09/24/2001	SERIAL # (LAST 7)	LG78309	FSDOC#	CUSTPERFORMED REPAIR?	DISTANCE UNITS	Y	MI/EB	
MFG CD	FTL	DATE FAILED	09/24/2001	COMPONENT TYPE	MAJOR COMPONENT	REPLACED	MODEL #	SERIAL #	
DISTANCE	85228	DATE REPAIRED	09/24/2001	PRIMARY FAILED PART	TDA A3 311172400				
B/O #	1000	REPLACED DISTANCE	8228						
SRT CODE	400-00508	HOURS	6.2	PART #	TDA A3 3111W8377	QTY	HH/L	PRICE EA	
					TDA A3 3111B3400	1	033	\$412.30	
						1	033	\$412.30	
TOTAL LABOR	260.00							\$824.60	
DAMAGE CODE 400-0026H740									
COMMENTS									
RIGHT KNUCKLE FAILED SEIZED UPON INSPECTION LEFT KNUCKLE NEAR FAILURE ALSO REPLACED.									
SUBLET	REFERENCE #	FREIGHT	OTHER	OUTSIDE TOTAL	CLAIM TOTAL				
					\$1084.80				

FIG. 14

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP																												
DOCULINK UNIT NUMBER: 1022352																																			
VIN: (ENTER LAST SIX DIGITS)				1FVYSBZY1G46309																															
MANUFACTURER:				FREIGHTLINER CORPORATION—FROHT																															
MODEL COMPONENT:				CENTURY GLASS-CONV. CEN DDE																															
PART NUMBER		PART DESCRIPTION		PART MFR.																															
<table border="1"> <thead> <tr> <th colspan="2">IMAGE INFORMATION</th> </tr> <tr> <th>IMAGE NAME</th> <th>IMAGE DESCRIPTION</th> </tr> </thead> <tbody> <tr> <td>400-C010707</td> <td>FF-381 SC1 S31L1447X48HS</td> </tr> <tr> <td>297-C030003</td> <td>FL90 EOF RPT, TRUCK</td> </tr> <tr> <td>771-C05704</td> <td>FLOOR COVER BAG AREA CRPTDBL IN</td> </tr> <tr> <td>772-C15407</td> <td>FLOOR COVER 70.MRRR.MATS</td> </tr> <tr> <td>126-T50083</td> <td>FLTR-CLNT FEG.D080.BLU RMTD</td> </tr> <tr> <td>703-C00353</td> <td>FLX CONV AC WIRECRC 1H.BINARY</td> </tr> <tr> <td>724-C02208</td> <td>FLX C101C12</td> </tr> <tr> <td>170-C02528</td> <td>FLX.DDC 80.ECR VALVE</td> </tr> <tr> <td>702-C01684</td> <td>FLX120-CAT 3408.88.BINARY.SAN</td> </tr> <tr> <td>166-C01901</td> <td>FLX.OIL.SRS60.DR450.ETN 70.SC</td> </tr> <tr> <td>567-C00204</td> <td>FRAME FASTENERS.HUCKSPIN</td> </tr> <tr> <td>546-C02602</td> <td>FRAME RAO 1018</td> </tr> </tbody> </table>								IMAGE INFORMATION		IMAGE NAME	IMAGE DESCRIPTION	400-C010707	FF-381 SC1 S31L1447X48HS	297-C030003	FL90 EOF RPT, TRUCK	771-C05704	FLOOR COVER BAG AREA CRPTDBL IN	772-C15407	FLOOR COVER 70.MRRR.MATS	126-T50083	FLTR-CLNT FEG.D080.BLU RMTD	703-C00353	FLX CONV AC WIRECRC 1H.BINARY	724-C02208	FLX C101C12	170-C02528	FLX.DDC 80.ECR VALVE	702-C01684	FLX120-CAT 3408.88.BINARY.SAN	166-C01901	FLX.OIL.SRS60.DR450.ETN 70.SC	567-C00204	FRAME FASTENERS.HUCKSPIN	546-C02602	FRAME RAO 1018
IMAGE INFORMATION																																			
IMAGE NAME	IMAGE DESCRIPTION																																		
400-C010707	FF-381 SC1 S31L1447X48HS																																		
297-C030003	FL90 EOF RPT, TRUCK																																		
771-C05704	FLOOR COVER BAG AREA CRPTDBL IN																																		
772-C15407	FLOOR COVER 70.MRRR.MATS																																		
126-T50083	FLTR-CLNT FEG.D080.BLU RMTD																																		
703-C00353	FLX CONV AC WIRECRC 1H.BINARY																																		
724-C02208	FLX C101C12																																		
170-C02528	FLX.DDC 80.ECR VALVE																																		
702-C01684	FLX120-CAT 3408.88.BINARY.SAN																																		
166-C01901	FLX.OIL.SRS60.DR450.ETN 70.SC																																		
567-C00204	FRAME FASTENERS.HUCKSPIN																																		
546-C02602	FRAME RAO 1018																																		

FIG. 15

ADOBE ACROBAT - (400 C10707.PDF)									
FILE EDIT DOCUMENT TOOLS PLUG-INS VIEW WINDOW HELP									

ADOBE ACROBAT - 400_C10707.PDF									
FILE EDIT DOCUMENT TOOLS PLUG-INS VIEW WINDOW HELP									

ADOBE ACROBAT - 1400_C10707.PDF									
FILE EDIT DOCUMENT TOOLS PLUGINS VIEW WINDOW HELP									

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
DIRECT PART NUMBER		FRGHT - FREIGHTLINER CORPORATION					
PART NUMBER		TDA A3 3111T3400		SEARCH			
PRIMARY CROSS REFERENCES(S):							
PART NUMBER (3)		PART MFR		VEHICLE SYSTEM			
400-C-10707		FRTRM - FREIGHTLINER BILL OF MATERIAL NUMBER					
A3 3111T3400		RCKIN - ROCKWELL INTERNATIONAL CORP. (NOW					
011-001		YMRSK - VEHICLE MAINTENANCE REPORTING STA					
PART DESCRIPTION (1)							
KNUCKLE ASSY RH							
APPLICATION DESCRIPTION (1)							
FF-981,S,C1,S31L14447X46HS							

FIG. 19

FleetCross		SEARCH METHODS		FILE		EDIT		TOOLS		HELP	
<div> </div>											
PARTS & LABOR GENERATOR											
VIN: (ENTER LAST SIX DIGITS):						UNIT NUMBER:					
1FUYSEB2YL64630						022352					
MANUFACTURER:											
FREIGHTLINER CORPORATION—FRGT											
MODEL OR COMPONENT:											
CENTURY CLASS L CONV CEN DDE											
VEHICLE SYSTEM:											
011001 - AXLE - FRONT NON-DRIVEN											
PARTS APPLICATION DESCRIPTION				REPAIR TIME APPLICATION				DAMAGE GROUP			
FF-981 S C1 S3 L1 4A47X46HS				FRONT AXLE ARM				400-000012			
				FRONT AXLE ASSEMBLY				400-000A10			
				FRONT AXLE BEAM				400-000085			
PARTS PER APPLICATION DESCRIPTION:											
PART NUMBER		PART DESCRIPTION				PART MFR					
TDA-A3 311T13400		KNUCKLE ASSY RH				FRGT					
LABOR OPERATIONS PER APPLICATION DESCRIPTION:											
SRT CODE		SRT DESCRIPTION									

FIG. 21







FleetCross	
SEARCH METHODS	FILE EDIT TOOLS HELP
     	
DIRECT PART NUMBER	
ROCKWELL INTERNATIONAL CORP. (NON MERITOR) PART NUMBER <input type="text" value="A3 311T3400"/> <input type="button" value="SEARCH"/>	
PRIMARY CROSS REFERENCE(S)	
(PART NUMBER (3)) TDA A3311T3400	PART MFR FRGHT - FREIGHTLINER CORPORATION
VEHICLE SYSTEM	
PART DESCRIPTION	
APPLICATION DESCRIPTION	

FIG. 22

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
PARTS & LABOR GENERATOR							
VIN: (ENTER LAST SIX DIGITS)		UNIT NUMBER					
1EJYSSB2VLG46309		022352					
MANUFACTURER:							
FREIGHTLINER CORPORATION—FRHT							
MODEL COMPONENT:							
CENTURY GLASS-LOW/ CEN DDE							
VEHICLE SYSTEM:							
011001 - AXLE - FRONT, NON-DRIVEN							
PARTS APPLICATION DESCRIPTION		REPAIR TIME APPLICATION		DAMAGE GROUP			
FF-981, S.C1.S311447X46HS		FRONT AXLE, KNUCKLE, SPN		400-002541			
		FRONT AXLE, KNUCKLE, STC		400-002580			
		FRONT AXLE, SCREW		400-600578			
PARTS PER APPLICATION DESCRIPTION:							
PART NUMBER		PART DESCRIPTION		PART MFR			
TDA A3 3111173400		KNUCKLE ASSY RH		FRHT			
LABOR OPERATIONS PER APPLICATION DESCRIPTION:							
ISRT CODE		ISRT DESCRIPTION					

FIG. 23





FIG. 25

☐ FleetCross [] [] [X]

SEARCH METHODS FILE EDIT TOOLS HELP



1000 [X]

WORK SUMMARY NUMBERS: DATE CREATED: CUSTOMER NAME:

1000 09/25/2001

VIN: 1HTSCAAM9WH555971 UNIT NUMBER: 178

MANUFACTURER:

INTERNATIONAL - NVSTR

MODEL OR COMPONENT:

4700 4X2

PARTS USED:

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.
NVSTR	1200818DC93	PUMP, POWER STRING	015005	1

PFI (PRIMARY FAILED ITEM)

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.

LABOR SUMMARY:

DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS
05000-701 K	A05-191	POWER STEERING PUMP R/R	015005	1.50


PRIMARY DAMAGED CODE: CAMPAIGN MEMBER: TOTAL HOURS: 1.50

05000-701 K ☐ ☐

FIG. 26

☐ FleetCross _ _ _ X

SEARCH METHODS FILE EDIT TOOLS HELP



☐ 1000 X

WORK SUMMARY NUMBERS: DATE CREATED: CUSTOMER NAME:

1000 10/03/2001

VIN: UNIT NUMBER:

854778 158-0714

MANUFACTURER:

VOLVO TRUCKS NORTH AMERICAQ - VLVNA

MODEL OR COMPONENT:

WG84

PARTS USED:

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.
VLVNA	8022509	CONDENSER, A/C	001001	1

PFI (PRIMARY FAILED ITEM)

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.

LABOR SUMMARY:

DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS
NONE	67401500	CONDENSER, REPL INCL R&R GRILLE	001001	1.50

PRIMARY DAMAGED CODE: CAMPAIGN MEMBER: TOTAL HOURS: 1.50

NONE ☐

FIG. 27